

# Lancaster CSD Water Sampling Remediation Plan

6.7.2021

					Initial Sample EPA Action Limit (ug/L)		Date Taken Out of Service				New Sample EPA Action Limit (ug/L)		Date Taken Out of Service		Planned Remediation Measure
Building	Central Ave	Location Within Building	Room 119 Sink	Initial Sample EPA Action Limit (ug/L)	17.5	Date Taken Out of Service	12/15/20	Planned Remediation Measure	Reflush	New Sample EPA Action Limit (ug/L)	23.5	Date Taken Out of Service	12/15/20	Planned Remediation Measure	To Be Determined
Building	Central Ave	Location Within Building	Womens lav across from 131, sink closest to door	Initial Sample EPA Action Limit (ug/L)	15.3	Date Taken Out of Service	12/15/20	Planned Remediation Measure	Reflush	New Sample EPA Action Limit (ug/L)	10.6	Date Taken Out of Service	service resumed 6.4.21	Planned Remediation Measure	Not applicable
Building	Central Ave	Location Within Building	Womens lav across from 131, sink closest to window	Initial Sample EPA Action Limit (ug/L)	31.3	Date Taken Out of Service	12/15/20	Planned Remediation Measure	Reflush	New Sample EPA Action Limit (ug/L)	<1	Date Taken Out of Service	service resumed 6.4.21	Planned Remediation Measure	Not applicable
Building	Central Ave	Location Within Building	Mens lav across from 131, sink closest to door	Initial Sample EPA Action Limit (ug/L)	21.8	Date Taken Out of Service	12/15/20	Planned Remediation Measure	Reflush	New Sample EPA Action Limit (ug/L)	24.9	Date Taken Out of Service	12/15/20	Planned Remediation Measure	To Be Determined
Building	Central Ave	Location Within Building	Mens lav across from 131, sink center left	Initial Sample EPA Action Limit (ug/L)	17.7	Date Taken Out of Service	12/15/20	Planned Remediation Measure	Reflush	New Sample EPA Action Limit (ug/L)	14.8	Date Taken Out of Service	service resumed 6.4.21	Planned Remediation Measure	Not applicable
Building	Central Ave	Location Within Building	Room 135 sink	Initial Sample EPA Action Limit (ug/L)	33.2	Date Taken Out of Service	12/15/20	Planned Remediation Measure	Reflush	New Sample EPA Action Limit (ug/L)	21.9	Date Taken Out of Service	12/15/20	Planned Remediation Measure	To Be Determined
Building	Central Ave	Location Within Building	Room 131 sink	Initial Sample EPA Action Limit (ug/L)	36.4	Date Taken Out of Service	12/15/20	Planned Remediation Measure	Reflush	New Sample EPA Action Limit (ug/L)	20.7	Date Taken Out of Service	12/15/20	Planned Remediation Measure	To Be Determined
Building	Central Ave	Location Within Building	Boys lav in main entry way, sink	Initial Sample EPA Action Limit (ug/L)	17.2	Date Taken Out of Service	12/15/20	Planned Remediation Measure	Reflush	New Sample EPA Action Limit (ug/L)	16.4	Date Taken Out of Service	12/15/20	Planned Remediation Measure	To Be Determined
Building	Como Park	Location Within Building	Room 114 bubbler	Initial Sample EPA Action Limit (ug/L)	181	Date Taken Out of Service	12/15/20	Planned Remediation Measure	Removed	New Sample EPA Action Limit (ug/L)	Not applicable	Date Taken Out of Service	12/15/20	Planned Remediation Measure	To Be Determined
Building	Como Park	Location Within Building	Room 207 sink	Initial Sample EPA Action Limit (ug/L)	15.4	Date Taken Out of Service	12/15/20	Planned Remediation Measure	Reflush	New Sample EPA Action Limit (ug/L)	15.2	Date Taken Out of Service	12/15/20	Planned Remediation Measure	To Be Determined
Building	Como Park	Location Within Building	Room 208 sink	Initial Sample EPA Action Limit (ug/L)	47	Date Taken Out of Service	12/15/20	Planned Remediation Measure	Reflush	New Sample EPA Action Limit (ug/L)	56	Date Taken Out of Service	12/15/20	Planned Remediation Measure	To Be Determined
Building	Como Park	Location Within Building	Room 204 sink	Initial Sample EPA Action Limit (ug/L)	18.2	Date Taken Out of Service	12/15/20	Planned Remediation Measure	Reflush	New Sample EPA Action Limit (ug/L)	21.7	Date Taken Out of Service	12/15/20	Planned Remediation Measure	To Be Determined
Building	Como Park	Location Within Building	Room 211 sink	Initial Sample EPA Action Limit (ug/L)	18.1	Date Taken Out of Service	12/15/20	Planned Remediation Measure	Reflush	New Sample EPA Action Limit (ug/L)	25.3	Date Taken Out of Service	12/15/20	Planned Remediation Measure	To Be Determined
Building	Como Park	Location Within Building	Room 223 sink	Initial Sample EPA Action Limit (ug/L)	18.9	Date Taken Out of Service	12/15/20	Planned Remediation Measure	Reflush	New Sample EPA Action Limit (ug/L)	23.1	Date Taken Out of Service	12/15/20	Planned Remediation Measure	To Be Determined
Building	Como Park	Location Within Building	Girls lav sink 220 far right	Initial Sample EPA Action Limit (ug/L)	16.6	Date Taken Out of Service	12/15/20	Planned Remediation Measure	Reflush	New Sample EPA Action Limit (ug/L)	4.94	Date Taken Out of Service	service resumed 6.4.21	Planned Remediation Measure	Not applicable
Building	Court Street	Location Within Building	Cafeteria kitchen hallway bubbler	Initial Sample EPA Action Limit (ug/L)	19.8	Date Taken Out of Service	12/15/20	Planned Remediation Measure	Removed	New Sample EPA Action Limit (ug/L)	Not applicable	Date Taken Out of Service	12/15/20	Planned Remediation Measure	To Be Determined
Building	Hillview	Location Within Building	Outdoor access Room 12 girls lav sink	Initial Sample EPA Action Limit (ug/L)	62.9	Date Taken Out of Service	12/14/20	Planned Remediation Measure	Reflush	New Sample EPA Action Limit (ug/L)	59	Date Taken Out of Service	12/14/20	Planned Remediation Measure	To Be Determined
Building	Hillview	Location Within Building	Outdoor access Room 9 boys lav sink	Initial Sample EPA Action Limit (ug/L)	41.9	Date Taken Out of Service	12/14/20	Planned Remediation Measure	Reflush	New Sample EPA Action Limit (ug/L)	27.8	Date Taken Out of Service	12/14/20	Planned Remediation Measure	To Be Determined
Building	John A. Sciole	Location Within Building	Room 1 sink	Initial Sample EPA Action Limit (ug/L)	23	Date Taken Out of Service	12/15/20	Planned Remediation Measure	Reflush	New Sample EPA Action Limit (ug/L)	35.4	Date Taken Out of Service	12/15/20	Planned Remediation Measure	To Be Determined
Building	John A. Sciole	Location Within Building	Faculty lav left sink	Initial Sample EPA Action Limit (ug/L)	n/a	Date Taken Out of Service	12/15/20	Planned Remediation Measure	Reflush	New Sample EPA Action Limit (ug/L)	1.8	Date Taken Out of Service	service resumed 6.4.21	Planned Remediation Measure	Not applicable
Building	John A. Sciole	Location Within Building	Room 18 sink	Initial Sample EPA Action Limit (ug/L)	n/a	Date Taken Out of Service	12/15/20	Planned Remediation Measure	Reflush	New Sample EPA Action Limit (ug/L)	2.4	Date Taken Out of Service	service resumed 6.4.21	Planned Remediation Measure	Not applicable
Building	John A. Sciole	Location Within Building	Outdoor restroom sink	Initial Sample EPA Action Limit (ug/L)	17.2	Date Taken Out of Service	12/15/20	Planned Remediation Measure	Reflush	New Sample EPA Action Limit (ug/L)	24.2	Date Taken Out of Service	12/15/20	Planned Remediation Measure	To Be Determined
Building	John A. Sciole	Location Within Building	Kitchen pan fill sink sprayer	Initial Sample EPA Action Limit (ug/L)	25.7	Date Taken Out of Service	12/15/20	Planned Remediation Measure	Reflush	New Sample EPA Action Limit (ug/L)	84.9	Date Taken Out of Service	12/15/20	Planned Remediation Measure	To Be Determined
Building	William Street School	Location Within Building	Kitchen serving area hand wash sink	Initial Sample EPA Action Limit (ug/L)	22.8	Date Taken Out of Service	12/14/20	Planned Remediation Measure	Reflush	New Sample EPA Action Limit (ug/L)	2.10	Date Taken Out of Service	service resumed 6.4.21	Planned Remediation Measure	Not applicable
Building	William Street School	Location Within Building	B106 sprayer	Initial Sample EPA Action Limit (ug/L)	16.8	Date Taken Out of Service	12/14/20	Planned Remediation Measure	Removed	New Sample EPA Action Limit (ug/L)	Not applicable	Date Taken Out of Service	12/14/20	Planned Remediation Measure	To Be Determined

# Lancaster CSD Water Sampling Remediation Plan

6.7.2021

[illegible]

## Lancaster CSD Water Sampling Remediation Plan

6.7.2021

[illegible]